

# TECHNICAL BULLETIN



**SILVER EAGLE**  
MANUFACTURING COMPANY

5825 NE Skyport Way, Portland, OR 97218  
1-800-547-6792

[www.silvereagle.com](http://www.silvereagle.com)

BULLETIN NO.:	TB06-003
DATE:	August 23, 2006
PAGE:	1 of 1

**REFERENCE:** Proper Use of the Eye/Chain Wear Gauge

**BACKGROUND:** The pictures below indicate the proper evaluation of lunette eye wear using the Silver Eagle gauge, part#15342



**FIRST “ZONE” —  
OK, MINIMAL WEAR**



**SECOND “ZONE” —  
18% WEAR, OK BUT  
APPROACHING  
REPLACEMENT.**

Does not “bottom out” anywhere  
in the eye’s wear area.



**THIRD “ZONE” —  
REPLACE**

“Bottoms out” anywhere in the  
eye’s wear area.

This bulletin and others can be found in the Silver Eagle website publications library:

<http://www.silvereagle.com/service/bulletins.asp>