

# TECHNICAL BULLETIN



**SILVER EAGLE**  
MANUFACTURING COMPANY

5825 NE Skyport Way, Portland, OR 97218  
(800) 547-6792 Fax: (503) 335-2171

BULLETIN NO.:	TB09-001
DATE:	November 3, 2009
PAGE:	1 of 1

## REFERENCE:                      **Stiff Leg Foot Pad Redesign**

**BACKGROUND:** Based on feedback from our customers we have redesigned our Stiff Leg Foot Pads. The pads were not being worn out, but instead the pad was delaminating from its plate and being lost. We have redesigned the foot leg pad to utilize a shoulder bolt and fender washers, which clamps the rubber pad in place. This secures the pad and prevents it coming loose and being lost. The fasteners used with the old pad will not work with the new design. As a result we have superseded part number 8808 to part number 9554 which includes the appropriate fasteners. Below is a photograph of the contents of the part number 9554 kit.

