

TECHNICAL BULLETIN



SILVER EAGLE
MANUFACTURING COMPANY

5825 NE Skyport Way, Portland, OR 97218
1-800-547-6792

www.silvereaglemg.com

BULLETIN NO.:	TB06-003
DATE:	August 23, 2006
PAGE:	1 of 1

REFERENCE: Proper Use of the Eye/Chain Wear Gauge

BACKGROUND: The pictures below indicate the proper evaluation of lunette eye wear using the Silver Eagle gauge, part#15342



**FIRST “ZONE” —
OK, MINIMAL WEAR**

ORIGINAL DIMENSION: 1.69"



**SECOND “ZONE” —
18% WEAR, OK BUT
APPROACHING
REPLACEMENT.**

1.69"-1.385"

Does not “bottom out” anywhere
in the eye’s wear area.



**THIRD “ZONE” —
REPLACE**

1.352" OR LESS

“Bottoms out” anywhere in the
eye’s wear area.

This bulletin and others can be found in the Silver Eagle website publications library:

<http://www.silvereaglemg.com/service/bulletins.asp>